

SOLUTIONS IN ENGINEERING JOB SAFETY ANALYSIS WORK SHEET FIRE SERVICES

ACTIVITY	HAZARDS	RISK CONTROL MEASURES	RESPONSIBLE
Using hand tools	Cuts / tears sprains etc.	Use tools in a manner that will not cause jamming or seizing. Wear appropriate PPE.	Contractor
Testing Equipment	False alarms	Ensure system is isolated before testing.	Contractor
Repairing / Rechargin g Equipment	Back injuries	Warm up prior to starting. Do not lift objects over 16kg per person. Use trolley to move heavy objects. Wear appropriate PPE.	Contractor
Repairing / Rechargin g Equipment	Chemical Hazards	Ensure chemicals are decanted in such a manner that there can be no pollution or spillage of chemicals away from the immediate area.	Contractor
Repairing / Rechargin g Equipment	Chemical Hazards	Ensure personnel using chemicals understand the hazards and those chemicals are stored appropriately. Ensure SDS's are available for all chemicals.	Contractor
Repairing / Rechargin g Equipment	Chemical Hazards	Ensure personnel using chemicals understand the hazards and wear appropriate PPE.	Contractor
Repairing / Rechargin g Equipment	Chemical Hazards to other persons	Ensure personnel using chemicals understand the hazards and establish a nogo area for other persons in the area. If other persons approach the area, immediately discontinue until persons have vacated.	Contractor

Repairing /	Chemical	Ensure chemicals are decanted in such a	Contractor
Rechargin	Hazards	manner that there can be no pollution or	
g		spillage of chemicals away from the	
Equipment		immediate area.	

NOTE: It is recommended that every Contractor complete and sign the Solutions in Engineering "Contractors Safe Working Agreement"
I have read the JSA Work Sheet and agree to comply with the guidelines as set out in the above mentioned documentation.
Contractor:
Signature: