

## JOB SAFETY ANALYSIS WORK SHEET GENERAL HANDY-MAN

ACTIVITY	HAZARDS	RISK CONTROL MEASURES	RESPONSIBLE
Gardening / Weeding	Back injuries	Warm up prior to starting. Do not lift objects over 16kg per person. Use trolley or wheelbarrow to move heavy objects. Wear knee pads when weeding.	Contractor
Gardening / Clean up	Cuts / scratches	Wear appropriate personal protective clothing.	Contractor
Gardening / Pruning	Working at height. Falling branches Electrical hazards	Do not use ladder over 2m high. Use cherry picker or scaffold. Check each branch for strength before resting ladder. Establish perimeter around area that is no-go area. Ensure there are no electrical cables in the vicinity of area.	Contractor
Gardening / Clean up	Insectbites / Broken glass / syringes / spiders	Wear appropriate foot and hand protection. Dispose of material in an appropriate manner.	Contractor
Using power tools	Noise / Vibration / Dust / Electrical hazards.	Wear appropriate personal protective equipment. Ensure all tools are appropriately guarded and electrical appliances are protected by means of a residual current device. Ensure all extension leads are in a safe condition with plugs and connections.	Contractor
Working outside	Sunburn	Sunhat / glasses / sunscreen / protective clothing.	Contractor
Gardening/Weeding	Back injuries	Warm up prior to starting. Do not lift objects over 16kg per person. Use trolley or wheelbarrow to move heavy objects. Wear knee pads when weeding.	Contractor
Gardening / Clean up	Cuts / scratches	Wear appropriate Personal Protective Clothing	Contractor

ACTIVITY	HAZARDS	RISK CONTROL MEASURES	RESPONSIBLE
Gardening / Pruning	Working at height. Falling branches Electrical hazards	Do not use ladder over 2m high. Use cherry picker or scaffold. Check each branch for strength before resting ladder. Establish perimeter around area that is no-go area. Ensure there are no electrical cables in the vicinity of area.	Contractor
Painting	Fumes / Dust	Ensure area is well ventilated and wear appropriate Personal Protective Equipment. Clean up after work.	Contractor
Painting	Pollution	Ensure paint is contained in area and that drop sheets are used whenever paint is opened or used.	Contractor
Painting	Hazardous / flammable materials	Ensure hazardous / flammable materials are stored in appropriate containers that are labelled and that Safety Data Sheets are available for each material stored.	Contractor
Painting	Hazardous / Flammable Materials	Ensure hazardous / flammable materials are stored in appropriate locations and volumes do not exceed allowable amounts.	Contractor

**NOTE: It is recommended that every Contractor complete and sign the Solutions in Engineering “Contractors Safe Working Agreement”**

I have read the JSA Work Sheet and agree to comply with the guidelines as set out in the above mentioned documentation.

Contractor:.....

Signature:.....Date:.....